EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
S1	2	("5980518").PN.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2007/03/12 17:16
S2 .	321517	(two second couple double pair another parallel) near3 (plate block flat face).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/12 17:31
S3	34	S2 and ((shear near3 stress) near3 (represent\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:58
S4	2	S3 and (microsensor surg\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:36
S5	4	S3 and (microsensor surg\$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:19
S6	350740	(two second couple double pair another fixed moving parallel) near3 (plate block flat face).clm.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2007/03/12 17:31
S7	39	S6 and ((shear near3 stress) near4 (represent\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/13 08:39
S8	2	S7 and (microsensor surg\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:58
S9 .	4	S7 and (microsensor surg\$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:37

EAST Search History

			-			
S10	269	((shear near3 stress) near3 (represent\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:58
S11	2	S10 and (microsensor surg\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/12 17:59
S12	25	S10 and (microsensor surg\$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/13 08:38
S13	10844	(73/760-860).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	OR ·	OFF	2007/03/13 08:38
S14	50	S13 and ((shear near3 stress) near4 (represent\$4 measur\$5 indicat\$4 meter\$4 test\$4 detect\$4 determin\$4 sens\$4 identi\$6 evaluat\$5 estimat\$5 transducer gauge cell monitor\$4 comput\$5 inspect\$5 meter calculat\$4)).clm.	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/13 08:43
S15	0	S14 and (microsensor surg\$5).clm.	US-PGPUB; USPAT; EPO; JPO	OR .	ON	2007/03/13 08:43
S16	3	S14 and (microsensor surg \$5)	US-PGPUB; USPAT; EPO; JPO	OR	ON	2007/03/13 08:43